

# Replacement Sheet

1/10




Figure 1




Figure 2



# Replacement Sheet

2/10




Figure 3

# Replacement Sheet

3/10




Figure 4 (i-v)

# Replacement Sheet

4/10




Figure 4 (vi-x)

# Replacement Sheet

5/10




Figure 5 (i-v)

# Replacement Sheet

6/10




Figure 5 (vi-xi)

# Replacement Sheet

7/10




Figure 6 (i-vi)

# Replacement Sheet

8/10

## Side View




Figure 7 (i-viii)




# Replacement Sheet

9/10


Side View

(i)



Step 1


(ii)



Coat A  
Coat resist R


Step 2

(iii)



Pattern resist  
Step 3


(iv)



Transfer resist  
slope by etching  
resist and A

Step 4

(v)



Step 5

Figure 8 (i-v)

# Replacement Sheet

10/10

## Side View




Figure 9 (i-v)